

Oil Field Environmental Incident Summary

Incident: 20150314150648

Date/Time of Notice: 03/14/2015 15:06

Responsible Party: Kevin Jacob

Well Operator: WHITE OWL ENERGY SERVICES, INC

Well Name: W.O. Watford #1

Field Name: SIVERSTON

Well File #: 90172

Date Incident: 3/13/2015

Time Incident: 15:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 98

Sec: 22

Qtr: NE SW

Location Description:

Submitted By: Kevin Jacob

Received By:

Contact Person: Kevin Jacob

12271 26F St NW

Watford City, ND 58854

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1000 Feet

Distance Nearest Water Well: 60 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	10	Barrels	10	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/13/2017

Clean Up Concluded: 3/13/2015

Risk Evaluation:

Mostly salt water contamination within the berm area

Areal Extent:

Potential Environmental Impacts:

soil within the berm area

Action Taken or Planned:

The rupture of the nipple was removed immediately and replaced with a schedule 80 hexagon 1/2" plug. The spill, as of this filing, has not been sucked out by a vacuum tractor/trailer, but we have been given assurances that a tractor/trailer will be available by 1800 tonight (3/14).

Wastes Disposal Location: The recovered waste will be disposed of within our own disposal system.

Agencies Involved:**Updates**

Date: 3/16/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.